


Back from the Brink



Wind erosion was threatening the stability of the Papamoa Surf Rescue Base (see the broken concrete at the front of the building, placed to reduce wind erosion of the foundations).



Planting native species and subsequent natural dune rebuilding have increased the stability of this important building, and created a wider beach for people to enjoy.