


Papamoa Domain Coastal Protection



Eroding Beach 1995



1997 photo. Beach width increasing following planting



Planting of native dune species in 1995 and 1996, and redirecting casual pedestrians has reversed earlier, ongoing erosion problems. Sand supplied by natural processes is being accumulated by the colonising dune plants (i.e. spinifex & pingao), burying fences, dramatically improving the dune buffer, and beach width.

Remnant of fence rail. The rest of the fence has been buried by accumulated sand.